Volvo Car Corporation Gothenburg, Sweden

Instruction No 31414316

Version 1.3 **Part. No.** 31414397, 31285189

Navigation system, RTI

Special tools	
	999 5919 PULLER (SEAL-PINION,CAM-CRANKSHAFT)B200-6304
	Tool number:999 5919
	Tool description:PULLER (SEAL-PINION,CAM-CRANKSHAFT)B200-6304
	Tool boards:46

Equipment VIDA IMG-242205 IMG-345497



Volvo Car Corporation Gothenburg, Sweden

Volvo Car Corporation Gothenburg, Sweden

Information

1

Read through all of the instructions before starting installation.

Notifications and warning texts are for your safety and to minimise the risk of something breaking during installation.


Ensure that all tools stated in the instructions are available before starting installation.

Certain steps in the instructions are only presented in the form of images. Explanatory text is also given for more complicated steps.

In the event of any problems with the instructions or the accessory, contact your local Volvo dealer.

Color symbols

2



Note!

This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

- Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4. Used when the component is not fully removed from the vehicle but only hung to the side.
- 5. Used for standard tools and special tools.
- 6. Used as background color for vehicle components.

IMG-363036


Removal

Volvo Car Corporation Gothenburg, Sweden

3





Note! Orientation view



Measure and mark as illustrated.


Volvo Car Corporation Gothenburg, Sweden






Use special tool: T9995919, PULLER (SEAL-PINION,CAM-CRANKSHAFT)B200-6304


Volvo Car Corporation Gothenburg, Sweden



Accessory installation



Volvo Car Corporation Gothenburg, Sweden



Download software (application) for the accessory's function according to the service information in VIDA.

Order and download software according to: 31414397

IMG-242268

10

Caution!

The car may need to be restarted up to 3 times after the application has been loaded in order for the activation of Navigation to be completed.